

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Pecan Grove Staging Area	Facility Location ID:	GR01
Assessment Date :	8/10/2010	Incident Name :	BP Spill
Physical Location :	9685 Firetower Road		
City, State :	Pass Christian, MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0
Additional Comments : 35 roll-offs on site labeled "oil contaminated material" (OCM). Two roll off containers (2134027 and 2134033) leaking minor amount of liquid. No oily sheen was observed on the ground surface. Facility representative stated that absorbent boom and pad will be placed immediately underneath each container to capture the liquid which will be placed in plastic bags and deposited into an OCM labeled container. All roll offs were covered, lined.	